

September 24, 2014

## Aurora Critical Update V1.0.9.6

This notice applies to all Aurora software users. Under some circumstances, previous versions of Aurora may not communicate card holder additions or edits to all Keyscan access control units. The result may be missing or inaccurate person information such as group permissions at some access control units.

Aurora version V1.0.9.6 has now been released and corrects the previously noted issue.

This Aurora software update is available for download on [www.keyscaan.ca/Aurora\\_Update.html](http://www.keyscaan.ca/Aurora_Update.html)

Keyscan strongly recommends that its customers stay, at all times, current with the very latest software versions. Integrators are urged to ensure the latest update to a minimum of Aurora V1.0.9.6 have been completed at all customers running Aurora along with performing an All Credentials Upload as instructed upon completion of the software update.

For further details please contact Keyscan Inc. and reference Critical Notice V1.0.9.6.

### Keyscan Technical Support

- Canada/USA – toll free: 1.888.539.7226
- Elsewhere: +1 905.430.7226
- Hours: Monday to Friday 9:00 AM to 6:30 PM Eastern Time